

06CTDPK6941A1ZZ

जय श्री कृष्ण
TAX INVOICEMob.: 9999247160
9785235333**Dev Electrical & Air Conditioning Solutions**

45, Main Road, Sallg KI Dhanl, Hayatpur, Gurugram (HR.)

E-mail: ajay25kumar1987@gmail.com

dev.airconditioning.sloution1987@gmail.com

DAIKIN

LG VOLTAS

HITACHI

Details of Receiver (Billed To)

State Code: 06

Rishumi Corporation Pvt Ltd

Sec 36A, Gurgaon.

SAAECV0565A1ZR

State Code: 06

Invoice No.: 013

Date: 31-03-21

Description of Goods	HSN Code	Qty.	Rate	Amount in Rs.
Service split		07	550	3850.00
capacitor Replace		01	750	750.00
l sensor		01	400	400.00
gas charge split AC - 2 Ton		02	3000	6000.00
wiring of panel ductable unit		03	1000	3000.00
valve		02	90	180.00
ductable unit PCB Card Repair		01	2400	2400.00
ductable unit gas charge 5 Ton		10 Ton	1800	18000.00
door Connector & Module		02	280	560.00
compressor Lead		01	300	300.00
door 32Amp 3 Pole Contactor		02	1800	3600.00
			Total	39040.00

BankName: **HDFC BANK**
 Account Number: **50200053298893**
 Branch IFSC Code: **HDFC0000485**

Total Invoice Amount in Words:

Thousand sixty seven rupees and
fifty Paise only

Total Amount to be Tax

Add: SGST@.....9.....% 3513.6

Add: CGST@.....9.....% 3513.6

Add: IGST@.....% -

Total Amount 46067.2

Terms & Conditions

1. We certify that we have valid registration under GST and all the
 informations are true and correct. 2. Our Goods & Services
 once sold cannot be taken back. 3. Our liability ceases after
 handover the goods to company. 4. This invoice is valid only
 Gurugram Jurisdiction. 5. E & O E.

For Dev Electrical & Air Conditioning Solutions



Authorized Signatory

DEV ELECTRICAL & AIR CONDITIONING SOLUTIONS

Deals in:- All type of electrical work, Air conditioning work, Cold room Refrigeration work, servicing and Repairing, new installation, AMC, building renovation work etc.

Add:- 45, B Block, Gali NO-5, Sheetla Colony, Gurgaon (H.R)

QUOTATION

- 1- Split Ac service - All Cabin split Ac service, Account office CEO Cabin & meeting rooms, Patwari Ji Cabin room.
- 2- Gas Charging - CEO cabin & near cabin gas charge in outdoor.
- 3- Ductable unit indoor coil sensor replace
- 4- Three ductable unit electrical panel checking & wiring
- 5- Pin valve replace in CEO cabin & meeting room.
- 6- Ductable unit ~~panel~~ Panel PCB Card repair near work station area.
- 7- 5 Ton ductable unit gas charging work station area, with 90 day warranty of Leakage.
- 8- Nitrogen gas filling charge for Test Leakage
- 9- Outdoor connector 6 module Replace
- 10- Compressor Lead Replace in outdoor CEO meeting room
- 11- room & contactor Replace 5 Ton outdoor unit

