

GSTIN : 06BYDPK5425K1ZC

Original Copy

TAX INVOICE
SHEETLA AIRCON

H.O : Jho Jhu Kalan , Tech.-ch. Dadri ,, Dist:- Bhiwani (HR)
B.O: Shop No 3,ganpati Honda Lane,ashok, Vihar Phase 3, Gurugram 122001 (HR)
PAN : BYDPK5425K
Tel. : 9718507366,9718507533 email : sheetla.aircon@rediffmail.com

Invoice No. : 2400273
Date of Invoice : 06-09-2024
Place of Supply : Haryana (06)

Reverse Charge : N
PO NO. :

Billed to :
KRISUMI CORPORATION PRIVATE LIMITED
CENTRAL PLAZA MALL 3RD FLOOR
DLF GOLF COURSE ROAD SECTOR 53
Gurgaon Haryana 122001

Shipped to :
KRISUMI CORPORATION PRIVATE LIMITED
CENTRAL PLAZA MALL 3RD FLOOR
DLF GOLF COURSE ROAD SECTOR 53
Gurgaon Haryana 122001

GSTIN / UIN : 06AAECV0565A1ZR

GSTIN / UIN : 06AAECV0565A1ZR

Order No. :

S.N.	Description of Goods	HSN/SAC Code	Qty.	Unit	Price	CGST Rate	CGST Amount	SGST Rate	SGST Amount	Amount()
1.	Compressor Split AC Voltas	84148011	1.00	Pcs.	11,500.00	9.00 %	1,035.00	9.00 %	1,035.00	13,570.00

GATE IN
NO. 1896
DATE 06/09/24
KRISUMI CORPORATION
Jachin

Grand Total 1.00 Pcs.

13,570.00

Tax Rate	Taxable Amt.	CGST Amt.	SGST Amt.	Total Tax
18%	11,500.00	1,035.00	1,035.00	2,070.00

Rupees Thirteen Thousand Five Hundred Seventy Only

Bank Details : BANK NAME = INDUSIND BANK / A/C NO. = 201000410545
IFSC CODE = INDB0000756 / BRANCH = PALAM VIHAR GURGAON

Terms & Conditions

E.& O.E.

1. Goods once sold will not be taken back.
2. Interest @ 18% p.a. will be charged if the payment is not made with in the stipulated time.
3. Subject to 'Haryana' Jurisdiction only.

Receiver's Signature :


For SHEETLA AIRCON
Authorised Signatory

Online payment on this bar code



SHEETLA AIRCON
Mob.: 9718507533, 9718507366
कम्प्लेट इन्ही मोबाईल पर वी स्वीकार हेमी।

Customer Contact Center
1860-180-3900
011-4031 9300
customerservice@daikinindia.com
Call Timing: 8 AM - 8 PM

Registration No.	Request Date	Service Engineer's Name	Schedule Date
		PANKAJ	31/07/24
User Name	Address		
KRISHMI KARPOTION	SEC-36A		
Mobile No.	Dealer Invoice No.		Tel No.
9568002890			
Daijin Invoice No.	Date	Date	
Type	Model No.	Date	Manufacturing No.
Indoor Unit	Outdoor Unit	Manufacturing No.	
EU 183 DYA		4551712	
Work Date	No. of Work Hours	Progress Code	Details of the Repair Work
			compressor change (Project office)
Compressor Manufacturing No.		Defective Compressor	Replacement Compressor
Installed Date	Warranty	AMC	Using With
	Yes / No	Yes / No	Stabilizer
			Cut-Off
			Yes / No
			Yes / No
Service Engineer Remarks			
Name: PANKAJ Signature: [Signature]			
Customer Remarks: New compressor installed but not proper cooling. So cooling is under observation			
Name: MANISH Signature: [Signature]			
Time		Notification No.	
Operation Date (Ambient Temp. °C)			
Before Repair		After Repair	
HP / T°C	psig/°C	psig/°C	psig/°C
SP / T°C	psig/°C	psig/°C	psig/°C
Current	Amps	Amps	Amps
Voltage	Volts	Volts	Volts
Indoor Temperature		Indoor Temperature	
Suction	°C	°C	°C
Discharge	°C	°C	°C
Outdoor Temperature		Outdoor Temperature	
Suction	°C	°C	°C
Discharge	°C	°C	°C
Work No. / Parts No.	Qty	Billing Amount	
compressor 1/1			
change			
R22 Gas charging	1/1		
Total			
Customer Impression About Service			
(Please rate on Scale of 1 poor, 2, 3, 4, & 5 Excellent)			
How is the behavior of Visited engineer			
What is the level of your Satisfaction			
How is the explanation by Engineer			
a Details of Repair Work Done			
b Simple Repair			
c Part Replaced			
d Gas Charging done			
e Routine Service - Wet			
f Routine Service - Dry			
Other			
Installation			
Unit			
Electrical			
Comp.			
FM			
PCB			
Power			
Fault Diagnosed			
Power Failure			
Phase Reverse			
In door unit PCB Defective			
Dirt door PCB Defective			
In door unit Fan Motor Defective			
D Indoor Fan Motor Defective			
Comp. taking High Current/Amp.			
Compressor Ground / Earth			
Compressor Tripping due to High Temperature			
Compressor Tripping due to High Pressure			
Indoor Unit Magsw Defective			
Dirt door Unit Magsw Defective			
Indoor Unit Transformer Faulty			
Out door Unit Transformer Faulty			
Fault of Spring Motor			
Defect of Drain Pump			
Expansion Valve Body / Motor Defective			
Defective Temperature Sensor of Indoor Unit			
Defective Temperature Sensor of Outdoor Unit			
Defective Current Sensor in Outdoor Unit			
Gas Leakage at Indoor Unit			
Gas Leakage at Outdoor Unit			
Elbow Broken			
Short Cycling of Air at Indoor Unit			
Short Cycling of Air at Outdoor Unit			
Defect in Drain Piping System			
Gas Leakage from Flare Nut			
Error in Transmission wiring			
F Product Under Capacity			
F Fit Bite Case			
Less Cooling Problem due to dirty Air Filter			
F Remote Setting Changed			
Clogged Condenser			
Other - Pl Specify			

"We recommend to take routine maintenance service of your Daikin Machine at regular intervals, for its good health."

FW: Sales Quotation



Sanjeet
To Ashok Kumar



31-07-2024

Dear sir,

Please see this quotation and if it is correct then approve it.

From: sheetla.aircon@rediffmail.com <sheetla.aircon@rediffmail.com>
Sent: Wednesday, July 31, 2024 3:16 PM
To: Sanjeet <sanjeet@krisumil.com>
Cc: Ashok Kumar <ashok.kumar@krisumil.com>
Subject: Sales Quotation

Dear sir,

Please find the attached sales quotation for compressor.

Thanks & Regards

Sanjeet

From: Sanjeet
Sent: 31 July 2024 16:25
To: Ashok Kumar
Subject: FW: Sales Quotation
Attachments: Sales_Quotation_-_SASQ2400046.pdf

Dear sir,

Please see this quotation and if is correct then approve it.

From: sheetla.aircon@rediffmail.com <sheetla.aircon@rediffmail.com>
Sent: Wednesday, July 31, 2024 3:16 PM
To: Sanjeet <sanjeet@krisumi.com>
Cc: Ashok Kumar <ashok.kumar@krisumi.com>
Subject: Sales Quotation

Dear sir,

Please find the attached sales quotation for compressor.

Thanks & Regards
Naveen Kumar

	Sheetla Aircon	
	DAIKIN Authorised Service Provider	
	Plot no. A78 New Palam Vihar 40 feet Road	
Gurgaon (HR.) 122017.
MOB. NO. 9718507366 / 8377986233

GSTIN : 06BYDPK5425K1ZC

Quotation

SHEETLA AIRCON

H.O : Jho Juu Kalan , Tech.-ch. Dadri ,, Dist:- Bhiwani (HR)
B.O: Shop No 3,ganpati Honda Lane,ashok, Vihar Phase 3, Gurugram 122001 (HR)
Tel. : 9718507366,9718507533 email : sheetla.aircon@rediffmail.com

Party Details :

KRISUMI CORPORATION PRIVATE LIMITED
CENTRAL PLAZA MALL 3RD FLOOR
DLF GOLF COURSE ROAD SECTOR 53
Gurgaon Haryana 122001

Quotation No. : SASQ2400046
Dated : 31-07-2024

GSTIN / UIN : 06AAECV0565A1ZR

S.N.	Description of Goods	HSN/SAC Code	Qty.	Unit	Price	CGST Rate	CGST Amount	SGST Rate	SGST Amount	Amount()
1.	Compressor Split AC Voltas	84148011	1.00	Pcs.	11,500.00	9.00 %	1,035.00	9.00 %	1,035.00	13,570.00

Grand Total 1.00 Pcs.

13,570.00

Tax Rate	Taxable Amt.	CGST Amt.	SGST Amt.	Total Tax
18%	11,500.00	1,035.00	1,035.00	2,070.00

Rupees Thirteen Thousand Five Hundred Seventy Only

PAYMENT TERMS

1. FOR SUPPLY OF EQUIPMENT 100% ADVANCE ALONG WITH P.O. (FOR HIGH SIDE)

FOR LOW SIDE :

(1) 30 % ADVANCE ALONG WITH P.O FOR SITE MOBILISATION AND ORDERING THE LOW SIDE MATERIALS. (2) 50% AGAINST DELERY OF MATERIAL.

(3) 10% AGAINST INSTALLATION OF MATERIAL. (4) 10% AGAINST TESTING & COMMISSIONING AND HANDING OVER OF SITES.

Bank Details : BANK NAME = INDUSIND BANK / A/C NO. = 201000410545
IFSC CODE = INDB0000756 / BRANCH = PALAM VIHAR GURGAON

Terms & Conditions

1. Prices are without any kind of Cil Work. If Required it Shall be in indiaculturecenter's Scope of works, However Minor Chipping drilling shall be done by us.
2.Power for Work shall be made available at site by client On free of cost basis.

Receiver's Signature :

For SHEETLA AIRCON
HARYANA
Authorised Signatory
GURUGRAM