

A.B.POWER SYSTEM2nd floor, House no-284, St no-6, Block A, Tomar Colony, Burari, Delhi, North Delhi – 110084

Mob- 7042965623, 7042850740, 9958540482

E-Mail- abpowersystem07@gmail.com, anshutomar4444@gmail.comWeb-www.abpowersystem.in

INVOICE NO: 33	OUR GTIN NO:07CUFPB9914H1ZL
DATE OF INVOICE:1 -MAY- 2024	OUR PAN NO : CUF9914H1

BILL TO: KRISUMI CORPORATION PVT LTD. SECTOR 36-A, NEAR VILLAGE-SIHI DWARKA EXPRESSWA, GURGAON HARYANA-122004	P.O.NO: Buyer's GSTIN/ ARN NO- 06MECV0565A1ZR PAN NO- Buyer's state code- Place Of Supply- Mode Of Transport-
---	--

S N O	Description of goods	SAC CODE	QTY	RATE	TOTAL	CGST		SGST		IGST	
						%	AMT	%	AMT	%	AMT
1	20 KVA UPS IT EMERSON SUPPLY CARD REPAIR CHARGES.	9954	1	8,000	8,000					18	1440
TOTAL					8,000	1440					

NAME OF ACC – A.B.POWER SYSTEMS	Rupees in Words..... NINE THOUSAND FOUR HUNDRED FOURTY ONLY. For A.B. POWER SYSTEM <i>D. S. Tomar</i> Proprietor	Total tax. Value	8,000
BANK NAME- INDIAN BANK		Discount	
A/C NO. - 50508822648		SGST@ 9 %	
IFSC CODE - IDIB000B886		CGST@ 9 %	
BRANCH - BURARI		IGST@ 18 %	1440
		GRAND TOTAL	9,440

Terms & conditions:

- Disputes if any, arising in this connection will be subject to Delhi jurisdiction only. Payment should strictly by made as per order. If payments are not made within the time as per order, we may disconnect the UPS and take back or switch off without prior information to the user.
- The UPS system and batteries supplied by us are premium brand for any malfunctioning of faulty, or if any loses or damage occur by the UPS system on batteries we held on responsibility.
- The ups system and batteries supply by us on RENT/HIRE are A.B.POWER SYSTEM property are now in customer custody. The customer is fully responsible for, if any misuse or damage due to elect. Fault, water or any liquid or fire, for A.B POWER system have no responsibilities. The customer Have to return the ups& batteries after uses In good working condition, if not A.B POWER system have right to claim the cost of UPS & BATTERIES.
- Payment should strictly by made as per order. If payments are not made within the time as per order, we may disconnect the UPS and take back or witch off without prior information to the user .

AB POWER SYSTEM

2nd Floor, Kh. No. 5/11, 12, 19, 20, Gali No. 6, Block-4, Tomar Colony, Village,
Burari, North Delhi, Delhi-110084

Mob. : 9958540482, 7042965623, 7042850740

E-mail : abpowersystem07@gmail.com, anshumantomar4444@gmail.com

Installation/Service Call Sheet

31/3/24

Call Received By :

<p>CUSTOMER'S NAME, ADDRESS & TELEPHONE NO.</p> <p>Krishomi Sales & Lounge Sector 36A Gurugram H.P.</p>	<p>REPORTED PROBLEM</p> <p>20KVA UPS Emerson 2T. Model.</p>
--	--

Job Deputed to _____ Under _____ Guarantee AMC Chargeable

Service Engineer *Arvind Kumar*

<p>SPECIFICATIONS :-</p> <p>1. Make of Equipment <i>20KVA UPS Emerson</i></p> <p>2. Capacity <i>20KVA</i></p> <p>3. Load Connected to Equipment <i>Light & Scissor</i></p>	<p>SERIAL NUMBER</p>
---	-----------------------------

<p>BATTERY :- <i>Exide 42AH. 12V.</i></p> <p>1. Make</p> <p>2. Capacity</p> <p>OBSERVATION :</p> <p>1. AC Input Volts <i>222, 225, 227 V</i></p> <p>2. Inverter Output <i>230, 230, 230,</i></p> <p>3. DC Output Volts <i>432V</i></p> <p>4. Battery Volts <i>420V</i></p> <p>5. Input Neutral to Ground Voltage <i>0.5</i></p>	<p>REPAIR ESTIMATE</p>
---	-------------------------------

Special Note to Customer :- *supply card fault
Repair card.*

Customer's Remarks :- *UPS is ok.*

Service Engineer Sign.

Date & Time

Arvind Kumar
31/3/24

Customer's Sign.

Date & Time

[Signature]
31/3/2024