

GSTIN : 06AGGPV5204K3Z5

TAX INVOICE

Mob.: 9999952266

0124-2225656

**GOOD AIR SERVICE**

A PERFECT COOLING SOLUTION

All Types of Air Conditioner Repair &amp; Service

Shop No. 13-14, H. No. 623/28, Near Sheetla Vidhya Peeth School, Gali No. 13 Jyoti Park, Gurugram-122006 (Hr.)

**VOLTAS AUTHORISED SERVICE CENTER**

Date &amp; Time of Removal

Bill No. **306**

P.O. No. &amp; Date

Date 19-07-2024

Details of Consignee (Shipped to)

Customer Name SanjeetAddress Narsinghpur KhandsaCity & State Cirugram, HaryanaMob. No. 9213248611 /Customer GSTIN 06AAECV0565A1ZR

Details of Receivers (Billed to)

Bank Details

GOOD AIR SERVICE  
STATE BANK OF INDIA  
A/c : 41452569227  
IFSC Code : SBIN0063056  
Mob.: 9999952266

No.	PARTICULARS	HSN Code	QTY.	Rate (Per Unit)	Total	CGST	SGST	Tax Value	Amount	
	PCB repair	9987	1	2550	2550	9%	9%	459	3009	
	labour charge	9987	1	500	500	9%	9%	90	590	
					<b>GATE IN</b> NO. <u>1010</u> DATE <u>19/07/24</u> <b>KRISUMI CORPORATION</b>					
									<b>For GOOD AIR SERVICE</b> <b>Proprietor</b>	

Invoice Total (in words) Three thousand Five hundred Ninety Ninerupees**TOTAL**3599E & O E.  
VOLTAS Helpline No. :  
18605994555, 9650694555For **GOOD AIR SERVICE**

Sign.

**Service Report**

Name	Krisumi Corporation	SR No	24071704164
Address	Kon,	Date	17-Jul-24 10:29 AM
Area	Khandsa, Default Area Selected	Phone	9213248611/
Pin, City Dist	122004, Narsinghpur, Gurgaon	Promo:	/
Key Account:	General P(P), General(S)	Appt. DT	18-Jul-24 6:00 PM
Symptom:	Breakdown -	Contact:	Krisumi Corporation
Remarks:	Position SR New API User : HTTPS Based API 2020	Phone #:	9213248611

**Unit Details**

Product	A/C Conditioner--	Model Name:	183 MYC
Unit Serial No. 1:	4511885617DB00737	Date of Purchase:	16-5-2017
Unit Serial No. 2:	4551839A17DA00814	Purchase From:	VOLVO LTD
Unit Status:	Warranty	Installed by:	

**Technical Details**

Earthing Stabilizer Tonnage/Room Size	OK	Not Ok	I/P Voltage:	210 V	Temperature Readings	
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	O/P Voltage:	231 V	Grill	13 deg C
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Current Drawn:	6.1 A	Room	26 deg C
					Ambient	34 deg C

**Technician Visit Details**

Fault Found:	PCR Repair	Action Taken:	Done
Date of Visit:	19-7-2024	Time of Visit: In:	1:12
Technician Name:	Alam, Shahanshah	Out:	
Cash Receipt No. & Date:		Cash Collected (Rs.):	

**Part Replacement Details**

Part Code	Part Description	Qty	Amount (Rs.)

**Customer Service Rating**

Excellent	Good	Average	Poor

5840  
Customer Name & Sign: *Vishay*

Customer Remarks: