

GSTIN:-06EBHPS0401K1Z0

ORIGINAL INVOICE

Tax Invoice

MR ENGINEERS

MR ENGINEERS C-1 GATE NEAR EKTA GROUP PALAM VIHAR ROAD, ASHOK VIHAR, GURUGRAM, HARYANA.-122001

Name- Krisumi Corporation Pvt.Ltd

Address :-Sec-36A, Near Sihl village ,Gurugram ( HR )

GSTIN:-06AAECV0565A1ZR

State:- HARYANA

INVOICE NO. :-

301

INVOICE DATE. :-

13-12-2022

STATE :

HARYANA

PO No:

PO Date :

S.No.	Name of the project / Service	HSN	UOM	Qty	Rate	Amount	Discount	Taxable Value	CGST		SGST		IGST		Total	
									Rate%	Amount	Rate %	Amount	Rate %	Amount		
1	PU Polish Work	1744	Sqft	499.5	85.00	42457.50		42457.50	9	3821	9	3821			50,099.85	
2	P-emiun Paint	3210	Sqft	380	17.5	6650.00		6650.00	9	599	9	599			7,847.00	
3	Apex Paint	3210	Sqft	266	17.5	4655.00		4655.00	9	419	9	419			5,492.90	
4	Miscellaneous Work		Lum-Sum	1	3500	3500.00		3500.00	9	315	9	315			4,130.00	
Total Amount In Work :								57262.50			5153.63			5153.63		67,569.75
Total Amount Before Tax:-																57263
ADD:CGST																5154
ADD:SGST																5154
ADD:IGST																5154
Total Amount After Tax:-																67570

Bank Name Branch - ?anjah National Bank

Bank Account Details - 09391131001891

Bank Branch IFSC- PUNB007110

Terms and Condition

01. All Disputes are subjected to Gurgaon Jurisdicit on Only

02. Payment will be P@airst Invoice

03. Interest will be Charged @24 against the late payment

04. Manufacture 's warranty / Guarantee applic@le on branded products only.

NO DATE 13/12/22  
 GATE IN 2114  
 KRISUMI CORPORATION  
 5/0  
 For MR ENGINEERS  
 Authorised Signatory

### Kapur Sir Visit

S.No.	Location	Uom	Qty	Requested By	Checked By	Verified By	Remarks
PU Polish Work							
1	Gents Visitor Washroom Main Door	Sqft	40	Smrta	[Signature]	Unseed	
2	Gents Visitor Washroom Vinior Polish	Sqft	46	Smrta	[Signature]	Unseed	
3	Gents Visitor Washroom Internal Door	Sqft	56	Smrta	[Signature]	Unseed	
4	Ladies Visitor Washroom Vinior Polish	Sqft	20.5	Smrta	[Signature]	Unseed	
5	Ladies Visitor Washroom Internal Door	Sqft	56	Smrta	[Signature]	Unseed	
6	Ladies Visitor Washroom Main Door	Sqft	35	Smrta	[Signature]	Unseed	
7	Aki Meeting room Door	Sqft	69	Smrta	[Signature]	Unseed	
8	Fuyu Meeting Room	Sqft	69	Smrta	[Signature]	Unseed	
9	CRM Entrance Door	Sqft	72	Smrta	[Signature]	Unseed	
10	Model Area ( Kitchen Floor )	Sqft	36	Smrta	[Signature]	Unseed	
	Total Area		499.5				
Premium Paint							
11	Pantry Area	Sqft	134	Smrta	[Signature]	Unseed	
12	Sample Apartment Bakony ( Front & Bottom )	Sqft	232	Smrta	[Signature]	Unseed	
13	Kapu - Sir Cabin	Sqft	14	Smrta	[Signature]	Unseed	
Apex Paint							
13	Sample Apartment Balcony Wall & Flower Pot )	Sqft	266	Unseed	Unseed	Unseed	
Miscellaneous							
14	Sample Tv Lounge Corner Repair	Lum-Sum		Unseed	[Signature]	Unseed	
15	AV Room ceiling	Lum-Sum		Unseed	[Signature]	Unseed	
16	Front of Aki Meeting ceiling Repair	Lum-Sum		Smrta	[Signature]	Unseed	
17	Haru Meeting Room Ceiling Repair	Lum-Sum		Smrta	[Signature]	Unseed	
18	Pantry Corner Repair	Lum-Sum		Unseed	[Signature]	Unseed	