

TAX INVOICE
MR ENGINEERS.

C-1, Near Ekta Group, Palam Vihar Road,
GSTIN : 06EBHPS0401K1ZQ
Tel. : 9911261305 email : mr.enggn@gmail.com

Invoice No. : 24 Dated : 01-12-2023 Place of Supply : Haryana (06) Reverse Charge : N GR/RR No. : Transport :	Vehicle No. : Station : SECTOR 53 E-Way Bill No. : PO No. : PO Date. :
Billed to : KRISUMI CORPORATION PRIVATE LIMITED 3RD FLOOR, CENTRAL PLAZA MALL DLF GOLF COURSE ROAD, SECTOR 53, Haryana 122001 GSTIN / UIN : 06AAECV0565A1ZR	Shipped to : KRISUMI CORPORATION PRIVATE LIMITED 3RD FLOOR, CENTRAL PLAZA MALL DLF GOLF COURSE ROAD, SECTOR 53, Haryana 122001 GSTIN / UIN : 06AAECV0565A1ZR

S.N.	Description of Goods	HSN/SAC Code	Qty.	Unit	Price	Amount(₹)
1.	Repairing Work (Civil) <i>Sales Office Roof Water Leakage Repair Work With Cellicon in Sheet Joint, MS Drain Cleaning Old Cellicon Removing And LDEP Sheet Fixing in Drain Area.</i>	9954	1.00	Job.	45,000.00	45,000.00
Add : CGST @ 9.00 % Add : SGST @ 9.00 %						45,000.00 4,050.00 4,050.00
Grand Total					1.00 Job.	₹ 53,100.00

Tax Rate	Taxable Amt.	CGST Amt.	SGST Amt.	Total Tax
18%	45,000.00	4,050.00	4,050.00	8,100.00

Rupees Fifty Three Thousand One Hundred Only

Bank Details : Bank - PNB BANK , BRANCH - NEW RAILWAY ROAD GURGAON
ACCOUNT NO - 09391131001891 , IFSC CODE- PUNB0007110

Terms & Conditions

E.& O.E.

- Goods once sold will not be taken back.
- Interest @ 18% p.a. will be charged if the payment is not made with in the stipulated time.
- Subject to 'Delhi' Jurisdiction only.

Receiver's Signature :

For M R ENGINEERS
for MR ENGINEERS.
For M R ENGINEERS
Proprietor
Authorised Signatory

MR ENGINEERS

C-1, Near Ekta Group Palam Vihar Road, Gurugram -122001

Mob-9911261305

GSTIN: - 06EBHPS0401K1ZQ

email-mr.engggn@gmail.com

Work Completion Certificate

To.

Ashok Jee (Krisumi Corporation Pvt Ltd.)

Sec36A, Gurgaon.

Subject - Work Completion Certificate for Water Leakage repair of sales lounge for Krisumi Sales Lounge.

We have completed water leakage repair work in sales lounge (Krisumi Sales Lounge) and sending you the letter to ensure that completed the work. All the work on our part has been completed.

We have done the water leakage testing.

You May Contact us for any further query or escalation.

Thanks & Regards

For M R ENGINEERS
Amin
Proprietor

MR Team

For M R ENGINEERS
Amin
Proprietor









